



**GCC Electrical  
Testing Laboratory**  
المفتبر الفليبي لفمص الممدات الكهريانية

## Distribution substation and verification of the earthing system

Background To familiarize with operation and maintenance of the MV and LV distribution substation.



**GCC Electrical  
Testing Laboratory**  
المفتبر الفليبي لفمص الممدات الكهريانية

Education  
Course Code: **M09**



**GCC Electrical  
Testing Laboratory**  
المفتبر الفليبي لفمص الممدات الكهريانية

## Distribution substation and verification of the earthing system

JULY  
22 - 26  
2018



# GCC Electrical Testing Laboratory

المختبر الفليبي لفحص المعدات الكهربائية

## Objectives

To familiarize with the calculation of the short circuit currents and the protection relays.

Addressed to:

Engineers Operating in the Maintenance of Industrial or Electrical Distribution Networks


Duration:

3 Full Days

Location/Venue:

GCCIA HQ, Dammam

Course Fees:



## PROGRAM

The Course program contains the following training outline:

### DAY 1

#### Electrical networks

- Basic layout of the electrical substation. Design rules according standards EN 61936-1
- Basic specification of the civil structures
- Functional characteristics of the main components
  - MV-LV transformers
  - MV Switchboards
  - LV switchboards
  - Voltage and current transformers
  - Substation automation
  - protections

### DAY 2

#### Earthing system and substation operations

- Earthing system
  - Basic requirements according standard EN 50522
  - Basic design of the earthing systems
  - Basic erection of the earthing systems
- Substation operation and maintenance
  - Single line diagrams
  - Protection devices operations
  - Typical commands and operations
  - Typical maintenance procedures

### DAY 3

#### Verification of the earthing system

- Safety requirements
- Earth potential rise
- Step voltage and touch voltage
- Soil electrical resistivity
- Method of measurement





Fig.1, Circulation of current through the end-user's grounding grid due to a ground fault on the primary side of the substation.